Dart Aerospace Ltd. Wednesday, 01/10/2008 9:50:53 AM Julie Lecocq **Process Sheet** Customer : CU-DAR001 Dart Helicopters Services **Drawing Name** : ARM Job Number : 42369 **Estimate Number** : 12882 P.O. Number **Part Number** : D3560042 : 01/10/2008 This Issue S.O. No. : **Drawing Number** : D3560 REV D Prsht Rev. : NC **Project Number** : N/A First Issue : // Type : MACHINED PARTS **Drawing Revision** : 41287 **Previous Run** Material **Due Date** Written By : 03/10/2008 Qty: 10 Um: Checked & Approved By Comment 07.05.24 EC New Issue **ECN 987** EC est rev B 07.10.09 verified by: DD ECN1048 Est Rev:C 07-12-18 verified by: EC **Additional Product** Job Number: Seq. #: **Machine Or Operation: Description:** 1.0 M6061T6B0500X05000 6061-T6 Bar .500 x 5.00 Comment: Qty.: 1.4648 f(s)/Unit *Total: 14.6475 f(s) 6061-T6 Bar 0:50" x 5.00" Batch: 2.0 BAND SAW Comment: BAND SAW Cut blanks 16.750" long 3.0 HAAS1 HAAS CNC VERTICAL MACHINING #1 Comment: HAAS CNC VERTICAL MACHINING #1 1- Mill as per Folio FA694 Rev: AA & Dwg D3560 Rev: 2-C'sink 0.196" hole on manual mill as per dwg D3560

3-Deburr per dwg D3560

INSPECT PARTS AS THEY COME OFF MACHINE

Comment: INSPECT PARTS AS THEY COME OFF MACHINE



(0)

Each

4.0

QC2

W/O:		WORK ORDER CHANGES								
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector			
•										
		•								
Part No	:	PAR #: Fault Category:	NCR: Y	es No DQ	A :	Date:				

Resolution: _____ Disposition: ____ QA: N/C Closed: ____ Date: ___

NCR:		WORK ORDER NON-CONFORMANCE (NCR)									
		Description of NC		Corrective Action Section B		Verification Section C	Approval Chief Eng	Approval QC Inspector			
DATE	STEP	Section A	Initial Chief Eng	Action•Description Chief Eng	Sign & Date						
,		North Control of the									
			ļ								
								:			
				,							

Dàte: Wednesday, 01/10/2008 9:50:53 AM User: Julie Lecocq **Process Sheet** Customer: CU-DAR001 Dart Helicopters Services Drawing Name: ARM Job Number: 42369 Part Number: D3560042 Job Number: Seq. #: **Machine Or Operation:** Description: 5.0 QC8 SECOND CHECK Comment: SECOND 6.0 D35921 Plate -Comment: Qty.: 1.0000 Each(s)/Unit Total: 10.0000 Each(s) 7.0 Comment: L'ARGE FABRICATION RESOURCE 1 1-Weld assembly as per dwg D3560 STEP: 1- clean material (buff bracket and bottom of arm with blue pad). 2- set up bracket and arm on jig 3- preheat bracket and arm with torch 4- clean before welding with brush 5- set up machine to 135 amps , 6- weld across bottom and top ends 7- reheat with torch (65 deg C) 8- on one side weld from bottom to top half way 9- same for other side (half way) 10- from half way point weld the rest of the first side (ease off pedal near end) -11- same for remaining side (ease off pedal near end) Comment: INSPECT WORK TO CURRENT STEP 9.0 QC9 VISUAL WELDING INSPECTION **Comment: VISUAL WELDING INSPECTION**

W/O:			WC	RK ORDER CHANG	GES				· · · · · · · · · · · · · · · · · · ·	
DATE	STEP	PROCEDURE CHANGE				Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
		•								
				*						
			•	÷						
		-								,
Part No	:	PAR #:	Fault Cate	gory:	_ NCI	R: Yes I	No DQ	A:	_ Date: _	
			Disposition: QA							
NCR:			WORK ORDE	R NON-CONFORM	ANCE	(NCR				
DATE	STEP	P Description of NC Section A	Corrective Action Section B			Verificatio			Approval	Approval
DATE	SIEF		Initial Chief Eng	Action Description Chief Eng		Sign & Date	Section C		Chief Eng	QC Inspector
	,						:			
		•								
					:					
										.
										-

Date: Wednesday, 01/10/2008 9:50:53 AM User: Julie Lecoca **Process Sheet** Customer: CU-DAR001 Dart Helicopters Services Drawing Name: ARM Job Number: 42369 Part Number: D3560042 Job Number: Seq. #: **Machine Or Operation:** Description: 10.0 HAND FINISHING1 HAND FINISHING RESOURCE #1 Comment: HAND FINISHING RESOURCE #1 Chemical Conversion Coat as per QSI 005 4.1 W) 11.0 QC3 INSPECT POWDER COAT/CHEMICAL CONVERS Comment: INSPECT POWDER COAT/CHEMICAL CONVERSION 12.0 D2808 Bushing Comment: Qty.: 1.0000 Each(s)/Unit Total: 10.0000 Each(s) Spacer 13.0 SMALL FAB SMALL & MEDIUM FAB RESOURCE 1 Comment: SMALL & MEDIUM FAB RESOURCE 1 1-Press bushing in D3560 arm per dwg D3562 14.0 QC5 INSPECT WORK TO CURREN Comment: INSPECT WORK TO CURRENT STEP 15.0 PACKAGING PACKAGING RESOURCE #1 Comment: PACKAGING RESOURCE #1 Identify and Stock Location: 16.0 QC21 FINAL INSPECTION/W/O RELEASE Comment: FINAL INSPECTION/W/O RELEASE MF 08-12-18 Job Completion

W/O:			W	ORK ORDER CHANG	SES					
DATE	STEP	PROCEDURE CHANGE			(Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
	Y									
•					.i			1		
					;					
Part No:		PAR #:	Fault Category:			R: Yes	A :	Date:		
Resolution:			Disposition:			: N/C C	Date: _			
NCR:		1	WORK ORD	ER NON-CONFORM	ANCE	E (NCI	₹)	-		
DATE	STEP	Description of NC			ection B		Verific	ation	Approval	Approval
DAIL	3127	Section A	Initial Chief Eng	Action Description Chief Eng		Sign of Date	Section	on C	Chief Eng	QC Inspector
		; 								
				· · · · · · · · · · · · · · · · · · ·						
					 					

DART AEROSPACE LTD	Work Order: 42369
Description: Arm	Part Number: D3560-2
Inspection Dwg: D3560 Rev: B	Page 1 of 1

FIRST ARTICLE INSPECTION CHECKLIST

X First Article Prototype

Drawing Dimension	Tolerance	Actual Dimension	Accept	Reject	Method of Inspection	Comments		
Ø0.507	+0.000/-0.001	Ø.5068	4					
Ø0.196	+0.005/-0.001	0.197	_					
Ø1.000	+0.010/-0.001	Ø1.003						
0.500	+/-0.010	. 493						
0.250	+/-0.010	.252						
0.275	+/-0.010	.275						
0.188	+/-0.010	188						
2.000	+/-0.010	2.000						
1.700	+/-0.010	1.750						
Ø0.385 x 100°	+/-0.010 x 0.5°	8.384 × 100°						
0.250 Deep	+/-0.010	258						
			-					
	-		,					
				_				
	-				-			
					-			
				<u> </u>				
				_				
					;			

Measured by:	Audited by:	Prototype Approval:	N/A
Date: 02/10/16	Date: 08/10/11	Date:	N/A

Rev	Date	Change	Revised by	Approved
<u>A</u>	07.01.17	New Issue	KJ/JLM , ,	
В	07.06.13	Dimensions updated per Dwg Rev B	KJ/JLM OK	E

			i i								
W/O:		· · · · · · · · · · · · · · · · · · ·	WO	RK ORDER CHANGE	S						
DATE	STEP	PROCEDURE CHANGE			Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector		
		•	·								
Part No:PA		PAR #:	Fault Categ	NCR: Yes No DQA: Date:							
Resolution:			Disposition	_ QA: N/C Closed: Date:							
NCR:		,	WORK ORDE	R NON-CONFORMAN	ICE (NC	R)					
DATE	STEP Description of NC Section A	Description of NC	Corrective Action Section			Verifi	Verification		Approval		
DATE		Section A	Initial Chief Eng	Action Description Chief Eng	Sign Dat		Section C	Approval Chief Eng	QC Inspector		
		i									
						Ì					
									1		
								[











